## SURVEYOR'S REAL PROPERTY REPORT

THIS DRAWING IS A REPRESENTATIVE OF THE CONDITIONS THAT WERE FOUND AT THE TIME OF THE REPORT. THIS REPORT WAS EITHER CONDUCTED BY THE LAND SURVEYOR OR UNDER HIS IMMEDIATE SUPERVISION. THIS DOCUMENT DOES NOT CONSTITUTE A BOUNDARY SURVEY AND IS SUBJECT TO ANY INACCURACIES THAT A SUBSEQUENT BOUNDARY SURVEY MAY DISCLOSE. PROPERTY CORNERS WERE NOT SET, AND THE INFORMATION SHOWN ON THIS DRAWING SHOULD NOT BE USED TO ESTABLISH ANY FENCE, STRUCTURE, OR ANY OTHER IMPROVEMENT. THE LINEAR OR ANGULAR VALUES SHOWN ON THIS DRAWING ARE BASED ON RECORD INFORMATION THAT HAS NOT BEEN VERIFIED. NO WARRANTY IS BEING EXTENDED TO PRESENT OR FUTURE OWNERS OR OCCUPANTS. OCCUPANTS.

## **MINNICK** SURVEYING

1244 DIELMAN INDUSTRIAL CT. ST. LOUIS, MO 63132 PHONE: (314) 721-9500 FAX: (314) 721-9501 MINNICKSURVEYING.COM



Date: XX/XX/20XX Grantee: SAMPLE, JOHN Grantor: SMITH, SAMPLE Premises: XXXX SAMPLE DRIVE, SAMPLE, MO

Subdivision Lot / City Lot: XX
Subdivision / City Block: SAMPLE SUBDIVISION
As recorded in: SAMPLE COUNTY RECORDS, PLAT BOOK XX, PAGE XX


Said premises were inspected on: XX/XX/XX

Description of ENCROACHMENTS or other VIOLATIONS:

None Visible

Made Exclusively For: SAMPLE TITLE/SAMPLE, JOHN





## SAMPLE DRIVE (50'W)

LEGEND						
PROPERTY LINE						
EASEMENT LINE						
BUILDING LINE						
ENCROACHMENT						
CONC						
WOOD STONE						
ASPH L GRAVEL						

0 	, 	15	5' I	30	)'	
SCALE: 1"=30'						
DRAW	1 B	Y: >	(XX	(		
ORDER	NO	).: >	XΧ	XXX	Χ	
DIMEN:	1012	1				
TOLER	ANC	Œ:	Χ.	.X'±		